CRITICAL TO QUALITY CLASSIFICATION TABLE					
P=PERFORMANCE, F=FIT, A=ASSEMBLY X=IDENTIFIES APPLICABLE CLASSIFICATION(S) ◇=ENGINEERING AND/OR MANUFACTURING REQUIREMENT Ⓡ=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY					
COMMENTS	DRAWING ZONE	◇P	◇F	◇A	ⒸR
ROHS	G1-H1				X













NOTE:
1. DIMENSIONS ARE IN MILLIMETERS



MUST COMPLY WITH ROCKWELL AUTOMATION ENVIRONMENTAL SPECIFICATION 970-20-01 Ⓡ

DIMENSION UNITS - mm	
UNLESS SPECIFIED THE FOLLOWING TOLERANCES APPLY (ISO/DIN MEDIUM).	
.X:±	N/A
.XX:±	N/A
ANG:±	N/A

ALL UNDIMENSIONED GEOMETRIES ARE CONTROLLED BY THE CAD MODEL. IN CASE OF DIMENSION DISCREPANCY, CAD MODEL OVERRIDES.

THIRD ANGLE PROJECTION

Rockwell Automation

DESCRIPTION: OUTLINE DRAWING 2198-SXXX-ERS4

CREATED BY:EMGARDNE | CHANGED BY:PTHAKRE

CONFIDENTIAL AND PROPRIETARY INFORMATION.
THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OF ROCKWELL AUTOMATION, INC., AND MAY NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL AUTOMATION, INC.

DATE:2021-09-06 | SHEET 1 OF 1

SIZE	DIR	VER
D	10006361825	00