




1 2 3 4 5 6 7 8


CRITICAL TO QUALITY CLASSIFICATION TABLE							
		P=PERFORMANCE, F=FIT, A=ASSEMBLY		X=IDENTIFIES APPLICABLE CLASSIFICATION(S)			
		◊=ENGINEERING AND/OR MANUFACTURING REQUIREMENT		◎=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY			
COMMENTS		DRAWING ZONE		P	F	A	R
ROHS		GI-HI					X
A							
B							
C							
D							
E							
F							
G							
H							



NOTE:
DIMENSIONS ARE SHOWN IN INCHES [MILLIMETERS]
DIMENSIONS ARE NOT INTENDED TO USE FOR MANUFACTURING PURPOSE

MUST COMPLY WITH ROCKWELL
AUTOMATION ENVIRONMENTAL
SPECIFICATION 970-20-01

ALL UNDIMENSIONED
GEOMETRIES ARE
CONTROLLED BY THE
CAD MODEL. IN CASE
OF DIMENSION
DISCREPANCY, CAD
MODEL OVERRIDES.



RA Rockwell
Automation

CUSTOMER DRAWING 1492-N1

CONFIDENTIAL AND PROPRIETARY INFORMATION.
THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY
INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY
NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT
WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL
AUTOMATION, INC.

DATE:2023-02-15 SHEET 1 OF 1

SIZE DIR VER
B B 00
10007238612 00

CREATED BY:BSOMAYAJI

CHANGED BY:-