


CRITICAL TO QUALITY CLASSIFICATION TABLE							
		P=PERFORMANCE, F=FIT, A=ASSEMBLY		X=IDENTIFIES APPLICABLE CLASSIFICATION(S)			
		◊=ENGINEERING AND/OR MANUFACTURING REQUIREMENT		◎=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY			
COMMENTS		DRAWING ZONE		P	F	A	R
ROHS		G-1					X




NOTE:

1. APPROXIMATE DIMENSIONS ARE SHOWN IN INCHES [MILLIMETERS].
 DIMENSIONS ARE NOT INTENDED TO BE USED FOR MANUFACTURING PURPOSES.

MUST COMPLY WITH ROCKWELL
 AUTOMATION ENVIRONMENTAL
 SPECIFICATION 970-20-01

ALL UNDIMENSIONED
 GEOMETRIES ARE
 CONTROLLED BY THE
 CAD MODEL. IN CASE
 OF DIMENSION
 DISCREPANCY, CAD
 MODEL OVERRIDES.



THIRD ANGLE PROJECTION



100-SCF,PROTECTIVE COVER FOR ACCESSORIES
 CUSTOMER DRAWING

CREATED BY:AKHAN24

CHANGED BY:-

CONFIDENTIAL AND PROPRIETARY INFORMATION.
 THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY
 INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY
 NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT
 WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL
 AUTOMATION, INC.

DATE:2024-03-28 SHEET 1 OF 1
 SIZE DIR VER
 B 10007888509 00