

NDTE:

R


H

1. DIMENSIONS ARE IN MM AND ARE FOR REFERENCE ONLY.


1

2

3



5



6

8									
CRITICAL TO QUALITY CLASSIFICATION TABLE P=PERFORMANCE, F=FIT, A=ASSEMBLY X=IDENTIFIES APPLICABLE CLASSIFICATION(S) S=ENGINEERING AND/OR MANUFACTURING REQUIREMENT R =REGULATORY REQUIREMENT - CONFORMANCE IS MANDATORY									
COMMENTS	DRAWING (ZONE)	$\langle \mathbf{P} \rangle$	F	$\langle A \rangle$	R				
ROHS	H1				х				

В

С

D

F

G

Η

7

6

Rockwell Automation		CONFIDENTIAL AND PROPRIETARY INFORMATION. THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL AUTOMATION, INC.						
DESCRIPTION SafeZone CIP Scanner Mounting Bracket 1		2020-04-20 DIR	SHEET	1	OF	1 VER		
CREATED BY SSHARM35 CHANGED BY	D							