


CRITICAL TO QUALITY CLASSIFICATION TABLE

P=PERFORMANCE, F=FIT, A=ASSEMBLY
 X=IDENTIFIES APPLICABLE CLASSIFICATION(S)
 ⬠=ENGINEERING AND/OR MANUFACTURING REQUIREMENT
 Ⓜ=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY

| COMMENTS | DRAWING ZONE | P | F | A | R |
|----------|--------------|---|---|---|---|
| ROHS | G1-H1 | | | | X |



MUST COMPLY WITH ROCKWELL
 AUTOMATION ENVIRONMENTAL
 SPECIFICATION 970-20-01

ALL UNDIMENSIONED GEOMETRIES
 ARE CONTROLLED BY THE CAD
 MODEL. IN CASE OF DIMENSION
 DISCREPANCY, CAD MODEL
 OVERRIDES.

THIRD ANGLE PROJECTION



60-2717 Photoelectric Accessory

CONFIDENTIAL AND PROPRIETARY INFORMATION.
 THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY
 INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY
 NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT
 WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL
 AUTOMATION, INC.

DATE: 2026-01-06 SHEET 1 OF 1

| DESCRIPTION | SIZE | DIR | VER |
|-----------------|------|-------------|-----|
| CREATED BY: SN5 | C | 10008856992 | 00 |
| CHANGED BY: - | | | |