










CRITICAL TO QUALITY CLASSIFICATION TABLE				
	P=PERFORMANCE, F=FIT, A=ASSEMBLY			
	X=IDENTIFIES APPLICABLE CLASSIFICATION(S)			
	◇=ENGINEERING AND/OR MANUFACTURING REQUIREMENT			
	⊙=REGULATORY REQUIREMENT-CONFORMANCE IS MANDATORY			
COMMENTS	DRAWING ZONE	◇	◇	◇
ROHS	GI-HI			X



MUST COMPLY WITH ROCKWELL AUTOMATION ENVIRONMENTAL SPECIFICATION 970-20-01

ALL UNDIMENSIONED GEOMETRIES ARE CONTROLLED BY THE CAD MODEL. IN CASE OF DIMENSION DISCREPANCY, CAD MODEL OVERRIDES.



Rockwell Automation

DESCRIPTION
CAT, 1756-EN4TRXT CUSTOMER DRAWING

CREATED BY: RUDDY CHANGED BY:

CONFIDENTIAL AND PROPRIETARY INFORMATION. THIS DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY INFORMATION OF ROCKWELL AUTOMATION, INC. AND MAY NOT BE USED, COPIED OR DISCLOSED TO OTHERS, EXCEPT WITH THE AUTHORIZED WRITTEN PERMISSION OF ROCKWELL AUTOMATION, INC.	
DATE: 2018-11-20	SHEET 1 OF 1
SIZE: D	VER: 00
10004446511	