



CRITICAL TO QUALITY CLASSIFICATION TABLE					
P=PERFORMANCE, F=FIT, A=ASSEMBLY					
X=IDENTITIES APPLICABLE CLASSIFICATION(S)					
⬠=ENGINEERING AND/OR MANUFACTURING REQUIREMENT					
Ⓜ=REGULATORY REQUIREMENT - CONFORMANCE IS MANDATORY					
COMMENTS	DRAWING (ZONE)	P	F	A	R
ROHS	H1				X

MUST COMPLY WITH ROCKWELL
SPECIFICATION 9702-01



DESCRIPTION
42EA RIGHTSIGHT S18A
18 MM RIGHT ANGLE MOUNT

CREATED BY

CHANGED BY

CONFIDENTIAL AND PROPRIETARY INFORMATION. THIS
DOCUMENT CONTAINS CONFIDENTIAL AND PROPRIETARY
INFORMATION OF ROCKWELL AUTOMATION, INC. AND
MAY NOT BE USED, COPIED OR DISCLOSED TO OTHERS,
EXCEPT WITH THE AUTHORIZED WRITTEN PERMISSION
OF ROCKWELL AUTOMATION, INC.

DATE 2021-05-10 SHEET 1 OF 1
SIZE DIR VER

D OUTLINE DRAWING 01